

AD-A173 868

AN INVESTIGATION OF THE FAA VERTICAL BUNSEN BURNER

1/1

FLAMMABILITY TEST METHOD(U) FEDERAL AVIATION

ADMINISTRATION TECHNICAL CENTER ATLANTIC CITY NJ


UNCLASSIFIED

P CAHILL AUG 86 DOT/FAA/CT-86/22

F/G 13/1

NL





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

2

DOT/FAA/CT-86/22

FAA TECHNICAL CENTER  
Atlantic City Airport  
N.J. 08405

# An Investigation of the FAA Vertical Bunsen Burner Flammability Test Method

Patricia Cahill

August 1986

Final Report

This document is available to the U.S. public  
through the National Technical Information  
Service, Springfield, Virginia 22161.



U.S. Department of Transportation  
Federal Aviation Administration

DTIC  
ELECTE  
NOV 4 1986  
S B

AD-A173 860

DTIC FILE COPY

86 11 3 056

#### NOTICE

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no liability for the contents or use thereof.

The United States Government does not endorse products or manufacturers. Trade or manufacturer's names appear herein solely because they are considered essential to the object of this report.

1. Report No. <b>DOT/FAA/CT-86/22</b>	2. Government Accession No. <b>10-1173860</b>	3. Recipient's Catalog No.	
4. Title and Subtitle <b>AN INVESTIGATION OF THE FAA VERTICAL BUNSEN BURNER FLAMMABILITY TEST METHOD</b>		5. Report Date <b>August 1986</b>	
		6. Performing Organization Code <b>ACT-350</b>	
7. Author(s) <b>Pat Cahill</b>		8. Performing Organization Report No. <b>DOT/FAA/CT-86/22</b>	
9. Performing Organization Name and Address <b>Federal Aviation Administration Technical Center Atlantic City Airport, New Jersey 08405</b>		10. Work Unit No. (TRAIS)	
		11. Contract or Grant No.	
12. Sponsoring Agency Name and Address <b>U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City Airport, New Jersey 08405</b>		13. Type of Report and Period Covered  <b>Final Report</b>	
		14. Sponsoring Agency Code	
15. Supplementary Notes			
16. Abstract <p>The vertical Bunsen burner test method, as specified in appendix F of the Federal Aviation Regulations - Part 25, was evaluated in order to update and clarify certain problem areas. Burner fuel, flame temperature and flame placement were investigated. It was determined that (1) methane gas can be used as a replacement or alternative to B-gas, (2) a minimum flame temperature specification is meaningless without specifying thermocouple wire thickness, and (3) placing the flame at the midpoint of the lower edge of the front face results in a more realistic and severe evaluation of the specimen's flammability properties.</p>			
17. Key Words <b>Flammability Tests Burner Fuel Flame Temperature Flame Placement Aircraft Fire Safety</b>		18. Distribution Statement  <b>Document is available to the U.S. public through the National Technical Information Service, Springfield, Virginia 22161</b>	
19. Security Classif. (of this report)  <b>Unclassified</b>	20. Security Classif. (of this page)  <b>Unclassified</b>	21. No. of Pages	22. Price

## TABLE OF CONTENTS

	Page
EXECUTIVE SUMMARY	v
INTRODUCTION	1
Purpose	1
Background	1
DISCUSSION	2
Burner Fuel	2
Flame Temperature	4
Flame Placement	6
SUMMARY OF RESULTS	8
CONCLUSIONS	9
REFERENCES	9
APPENDIX	

# LIST OF ILLUSTRATIONS

Figure		Page
1	B-Gas Flames	6
2	Methane Gas Flames	7
3	Average Flame Temperatures	8
4	Effect of Flame Placement on Composite Burn Results (Thickness 1/8, 1/4 Inch)	9
5	Effect of Flame Placement on Composite Burn Results (Thickness 3/8, 1/2 Inch)	10
6	Effect of Flame Placement on Composite Burn Results (Thickness 3/4, 1 Inch)	11
7	Effect of Flame Placement on Composite Burn Results (Front Face, Back Face)	12
8	Effect of Flame Placement on Foam Burn Results	13



Accession For	
NTIS GPO	✓
DTIC TAB	
Unannounced	
Justification	
By _____	
Distribution _____	
Availability _____	
Dist	Avail. or Spec.
A-1	

## EXECUTIVE SUMMARY

This report contains the results of an evaluation of the vertical Bunsen burner test method as specified in appendix F of the Federal Aviation Regulations (FAR) Part 25. Burner fuel, flame placement, and flame temperature were evaluated.

The currently used burner fuel, B-gas, was compared to methane gas. Test results show that burn length and flame time are similar for both gases when the gases are fresh. However, a chemical reaction occurs with aging in B-gas between carbon monoxide and the iron in the steel cylinder, making it difficult to consistently regulate flame height. This problem is eliminated with the use of methane gas.

Flame placement was evaluated for test specimens ranging up to 1 inch in thickness. It was found that placing the flame at the midpoint of the lower edge of the front face resulted in a more realistic and severe evaluation of the test specimen's flammability properties. This applies to all specimens regardless of thickness. With the exception of foam, burn results show that it is necessary to test both front and back faces of test specimens 1/2 inch and greater to ensure a realistic assessment of surface flammability.

Flame temperature experiments were carried out using various thermocouple gauge sizes. Test results show that an inverse relationship exist between flame temperature and thermocouple gauge size. Therefore, a minimum flame temperature specification is meaningless without specifying the thermocouple gauge size.



## INTRODUCTION

### PURPOSE.

The purpose of this report is to present the results of an investigation of the vertical Bunsen burner test method as specified in appendix F of the Federal Aviation Regulations (FAR) Part 25.

### BACKGROUND.

In 1951, Federal Specification CCC-T-191b, "Textile Test Methods" was issued for government procurement purposes. It included a horizontal flammability test for cloth, Method 5906, and a vertical flammability test for cloth, Method 5902, whose general apparatus and procedures were eventually used in Federal Aviation Administration (FAA) regulations.

In 1967, Amendment 15 for FAR Part 25 was issued by the FAA. This Amendment did not reference the CCC-T-191b methods, but instead, documented the test procedure with reference to Method 5902 in appendix F of FAR 25.

In 1968, Federal Test Method Standard (FTMS) 191 replaced CCC-T-191b. Method 5903 replaced Method 5902 which was dropped at the time of this change. Method 5903 differed from Method 5902 in that it specified a particular gas mixture for use as burner fuel.

The vertical Bunsen burner test method has evolved into a certification and quality control flammability test for a wide variety of aircraft interior materials (honeycomb, composites, plastic sheets, foams, fiberglass insulation, etc). It has been proven to be an effective and convenient test procedure. Nonetheless, over the years, a number of problem areas have arisen, some traceable to the original test procedure being intended for cloth materials, that create inconsistencies in data. This report presents an investigation of several of the most pertinent problem areas with the aim of producing a more clear and concise test procedure that will reduce the likelihood of ambiguous or inconsistent data.

## DISCUSSION


### BURNER FUEL.

Appendix F of FAR Part 25 specifies a particular gas mixture for use as Bunsen burner fuel by reference to FTMS-191 - Method 5903, "Flame Resistance of Cloth; Vertical." This specific gas mixture is commonly referred to as B-gas. However, it is sold by different trade names, depending on the gas producer. As an example, Matheson Gas Products call the gas mixture "Flame Resistance of Cloth Test Gas." Components of the gas mixture are specified as follows:

Hydrogen	55 ± 1%
Methane	24 ± 1%
Ethane	3 ± 1%
Carbon Monoxide	18 ± 1%

Many testing facilities have stated that B-gas produces inconsistent flame characteristics from cylinder to cylinder. Furthermore, this inconsistency is reflected

in variable test results. Evaluation of the B-gas has verified that inconsistent flame characteristics do indeed exist from cylinder to cylinder. Figure 1, photographs a, b, and c, show actual B-gas flames from three different cylinders of various ages (age listed under each photograph). The characteristics of the three B-gas flames are vividly different. Photograph c shows an especially elongated and intensely orange-spiked flame while a double cone formation is shown in photograph b. Laboratory evaluation of both flames confirmed the presence of an iron oxide compound ( $\text{Fe}_2\text{O}_3$ ) emanating from the flame.  $\text{Fe}_2\text{O}_3$  is a product of the reaction:



Iron pentacarbonyl is a colorless to yellow oily liquid and is formed by the reaction of carbon monoxide (CO) with iron (Fe). The primary source of iron is the steel cylinder in which the B-gas is contained. In effect, what is seen in photograph c of figure 1 is the atomic spectrum of iron, while photograph b depicts an intermediate stage. As the cylinder ages, more iron pentacarbonyl is formed, ultimately resulting in the flame characteristic seen in photograph c. The formation of a spike or double cone in the burner flame makes it difficult to adjust the burner to give a flame of 1 1/2 inches in height as specified in appendix F of FAR, Part 25. More importantly, as the flame characteristics are altered with age, the intensity of the flame and the resulting material sample burn characteristics will also change.

Methane gas of 99 percent purity was tested as a substitute for B-gas. Referring to figure 2, note the well defined diffusion flame of the methane gas. The blue reaction zone can be seen on the outside of the luminous carbon zone, and reaches to the top of the flame. Flame height is well defined and easily regulated as a result of this well defined flame tip. In order to compare B-gas with methane, various materials were tested. Referring to table 1, it can be seen that burn lengths and flame times are very similar for both gases.

#### FLAME TEMPERATURE.

Appendix F of FAR, Part 25 requires that the minimum flame temperature in the center of the flame be at least  $1550^\circ\text{F}$  for the vertical burn test. This temperature minimum is also required for the horizontal and 45-degree tests. The 60-degree test specifies a minimum temperature of  $1750^\circ\text{F}$  in the hottest portion of the flame. A calibrated thermocouple pyrometer is specified for temperature measurement. However, no particular thermocouple gauge size is required.

A number of experiments, employing five different gauge size thermocouples, were performed in order to examine flame temperature in the center of the flame. Flame height (1 1/2 inches), gas delivery pressure ( $2 \frac{1}{2} \pm \frac{1}{4}$  pounds psi), and all other requirements were followed according to the rule. An in-line needle valve was used to regulate gas flow. The Bunsen burner base had a 1.5 mm orifice diameter. Other bases with orifice diameters as small as 0.67 mm were evaluated with no significant test result differences. However, the base with the 1.5 mm orifice produced a conical flame with complete flame impingement around the burner mouth and, therefore, was used in all testing. The thermocouples were inserted into the flame horizontally. For comparison, B-gas and methane flame temperatures were evaluated. From figure 3, it can be seen that flame temperature and thermocouple gauge size are inversely proportional to each other. The 36-gauge Chromel Alumel thermocouple reflects the highest average temperature for both gases while the lowest average temperature is seen with the 20-gauge thermocouple.

TABLE 1. VERTICAL BURN TEST RESULTS

SAMPLE	DESCRIPTION	Average of 3 Samples			
		Flame Time (sec)		Burn Length (in.)	
		Methane	B-gas	Methane	B-gas
Carpet	90/10 Wool Nylon Warp Dir.*	2.7	2.2	1.3	1.2
Carpet	90/10 Wool Nylon Weft Dir.*	2.4	1.9	1.2	1.2
Carpet	85/15 Wool Nylon Warp Dir.	6.1	7.0	2.4	2.7
Carpet	85/15 Wool Nylon Weft Dir.	3.6	4.0	2.1	2.3
Upholstery	90/10 Wool Nylon	1.0	0.7	2.1	1.6
Drapery	35/65 Wool Synthetic	0	0	3.3	2.7
Ceiling Panel	<u>Tedlar Finish</u> <u>Epoxy/Fiberglass Facings</u> <u>Phenolic/Nomex Core</u>	0	0	3.3	3.2
Sidewall Panel	<u>Tedlar Finish</u> <u>Epoxy/Fiberglass Facings</u> <u>Phenolic/Nomex Core</u>	0	0	3.4	3.8
Partition	<u>Tedlar Finish</u> <u>Epoxy/Fiberglass Facings</u> <u>Phenolic/Nomex Core</u>	0	0	1.9	1.6
Stowbin Shelf	<u>Tedlar Finish</u> <u>Epoxy/Fiberglass Facings</u> <u>Phenolic/Nomex Core</u>	0	0	1.5	1.1
Flooring	Carbon/Epoxy <u>Facings</u> Nomex/Phenolic <u>Core</u>	0	0	1.6	2.1

\* Tested in warp direction - yarns extended lengthwise

\* Tested in weft direction - crossing yarns

It is known that wire (in this case, thermocouple wire) will normally be cooler than the flame gases, owing to heat losses by radiation, conduction, and convection. Thus, as the thickness of the thermocouple wire is decreased, the closer the measurement to the real flame temperature. There is obviously a limit set by the mechanical strength of the wire for the smallest diameter thermocouple wire that can be practically utilized; therefore, nothing finer than 36-gauge wire was tested.

Referring to figure 3, both the B-gas and methane flames show an average temperature of 2300° F in the center of the flame when measured with the 36-gauge thermocouple. According to Hassian and Russel, theoretical flame temperature for methane exceeds 3000° F (reference 2), thus, the measurement was reasonable and, perhaps, still below the true flame temperature.

#### FLAME PLACEMENT.

According to appendix F of FAR Part 25, the flame for the vertical burn test must be applied to the center line of the lower edge of the specimen. This is an ambiguous statement since it does not specify a point, but a line.

While initially a cloth materials test, the vertical burn test now encompasses interior aircraft composite materials such as class partitions which can range over one inch in thickness. For this reason, flame placement must be clearly identified.

Interior ceiling panels, wall panels, cabinet walls, structural flooring, etc., are generally sandwich composites. The composites are fabricated by bonding resin systems such as epoxies or phenolics to a honeycomb core material with an adhesive. While core materials such as balsa, glass, and aluminum are used in certain applications, core material used in aircraft composite panels is primarily an aromatic polyamide sold under the trade name of Nomex™. Testing with the Bunsen burner has shown Nomex honeycomb core to be self-extinguishing.

At the present time, the burner is positioned under the geometric center of the bottom surface of the test specimen. This is common practice in most test facilities. However, testing has shown that placing the flame on the midpoint of the lower edge of the front face produces test results that best represent the specimen's overall flammability properties. Figures 4, 5, and 6 depict various panels of different thicknesses burnt with the flame placed in the geometric center of the bottom surface and also on the midpoint of the lower edge of the front face.

No distinguishable difference in burn length can be seen for the thin specimens shown in figure 4. However, the differences are obvious when viewing the thicker panels shown in figures 5 and 6. For samples 1/2 inch and greater, geometric center flame placement does not give test results representative of the material's total flammability properties. This is due to flame impingement primarily on the self-extinguishing honeycomb core.

Referring to figure 7, note the absence of flame impingement on the back face of the panel. While flame placement on the midpoint of the lower edge of the front face gives more realistic test results, it was found that it is necessary to test the back face as well for samples 1/2 inch and greater. One test specimen, however, may be used for both front and back face testing.

According to appendix F of FAR, Part 25 thick foam parts, such as seat cushions, must be tested in 1/2-inch thickness. Referring to figure 8, flame placement on the midpoint of the lower edge of the front face resulted in a melting away of the material. However, the burn length is the same as the sample with geometric center flame placement. For foam test specimens, it is not necessary to separately test front and back faces. Unlike composite materials or carpets with different backings, polyurethane foams are homogeneous.

#### SUMMARY OF RESULTS


1. Burn length and flame time values are similar for both B-gas and methane when used as burner fuel if the B-gas flame characteristics have not been altered by aging. It appears that the change in the flame characteristics of B-gas with aging is a result of chemical reactions with the iron in steel storage cylinders.
2. Flame height is much easier to regulate with methane as opposed to B-gas due to methane's reproducible flame characteristics.
3. Placing the flame on the midpoint of the lower edge of the front face of composite test specimens produces more realistic and severe test results than placing the flame in the geometric center of the bottom face.
4. With the exception of foam, flammability properties of test specimens 1/2 inch and greater in thickness are best represented by testing the back face in addition to the front face (one test specimen may be used for both tests).
5. An inverse relationship exists between the measured flame temperature and thermocouple gauge size.

#### CONCLUSIONS


1. Methane gas can be used as a replacement or alternative to B-gas as Bunsen burner fuel because it produces similar flame characteristics and does not experience an alteration in flame characteristics as a result of storage cylinder aging effects.
2. Placement of the burner flame at the geometric center of the specimens bottom edge does not give a realistic and severe assessment of surface flammability for composite materials.
3. With the exception of foam, all test specimens 1/2 inch and greater in thickness should be tested on both front and back faces in order to assess surface flammability.
4. A minimum temperature specification is unnecessary and meaningless without a thermocouple gauge size specified.

#### REFERENCES


1. Guastavino, T., Federal Aviation Administration Analytical Chemistry Laboratory, Quality Control Notebook, Page 17, 1986.
2. Hasian, R., and Russel, R., Fuels and Their Combustion, McGraw Hill, New York, 1929.



A.  
**1 MONTH**



B.  
**6 MONTHS**



C.  
**18 MONTHS**

FIGURE 1. B-GAS FLAMES



U.S. TECHNICAL CENTER  
ATLANTIC CITY, NEW JERSEY

86 - 0642

FIGURE 2. METHANE GAS FLAMES

# AVERAGE FLAME TEMPERATURES





FIGURE 3. AVERAGE FLAME TEMPERATURES





**GEOMETRIC CENTER  
FLAME PLACEMENT**



**MIDPOINT-LOWER  
EDGE-FRONT FACE  
FLAME PLACEMENT**

**SIDEWALL PANEL  
THICKNESS-1/8 INCH**




**GEOMETRIC CENTER  
FLAME PLACEMENT**



**MIDPOINT-LOWER  
EDGE-FRONT FACE  
FLAME PLACEMENT**

**CEILING PANEL  
THICKNESS-1/4 INCH**

**FIGURE 4. EFFECT OF FLAME PLACEMENT ON COMPOSITE BURN RESULTS  
(THICKNESS 1/8, 1/4 INCH)**



**GEOMETRIC CENTER  
FLAME PLACEMENT**




**MIDPOINT-LOWER EDGE-  
-FRONT FACE  
FLAME PLACEMENT**

**FLOORING  
THICKNESS -  $\frac{3}{8}$  IN.**



**GEOMETRIC CENTER  
FLAME PLACEMENT**



**MIDPOINT-LOWER EDGE-  
-FRONT FACE  
FLAME PLACEMENT**

**STOWBIN SHELF  
THICKNESS -  $\frac{1}{2}$  IN.**

**FIGURE 5. EFFECT OF FLAME PLACEMENT ON COMPOSITE BURN RESULTS  
(THICKNESS  $\frac{3}{8}$ ,  $\frac{1}{2}$  INCH)**



**GEOMETRIC CENTER  
FLAME PLACEMENT**



**MIDPOINT-LOWER  
EDGE-FRONT FACE  
FLAME PLACEMENT**

**CEILING PANEL  
THICKNESS- $\frac{3}{4}$ IN.**




**GEOMETRIC CENTER  
FLAME PLACEMENT**




**MIDPOINT-LOWER  
EDGE-FRONT FACE  
FLAME PLACEMENT**

**CEILING PANEL  
THICKNESS-1 INCH**

PHOTOGRAPHS OF FIRE TESTS CONDUCTED AT THE NATIONAL BUREAU OF STANDARDS, WASHINGTON, D. C.



**GEOMETRIC CENTER  
FLAME PLACEMENT**



**MIDPOINT-LOWER EDGE-  
FRONT FACE  
FLAME PLACEMENT**

**CEILING PANEL  
FRONT FACE**



**GEOMETRIC CENTER  
FLAME PLACEMENT**




**MIDPOINT-LOWER EDGE-  
FRONT FACE  
FLAME PLACEMENT**

**CEILING PANEL  
BACK FACE**

**FIGURE 7. EFFECT OF FLAME PLACEMENT ON COMPOSITE BURN RESULTS  
(FRONT FACE, BACK FACE)**



**GEOMETRIC  
CENTER-FLAME  
PLACEMENT**



**MIDPOINT-LOWER  
EDGE-FRONT FACE**

**POLYURETHANE  
FOAM  
THICKNESS- $\frac{1}{2}$  INCH**

**FIGURE 8. EFFECT OF FLAME PLACEMENT ON FOAM BURN RESULTS**

# APPENDIX A

## DISTRIBUTION LIST

Civil Aviation Authority (5)  
Aviation House  
129 Kingsway  
London WC2B 6NN England

DOT-FAA AEU-500 (5)  
American Embassy  
APO New York, NY 09667

Embassy of Australia (1)  
Civil Air Attache  
1601 Mass. Ave. NW  
Washington, DC 20036

University of California (1)  
Service Dept Institute of  
Transportation Standard Lib  
412 McLaughlin Hall  
Berkely, CA 94720

Scientific & Tech. Info FAC (1)  
ATTN: NASA Rep.  
P.O. Box 8757 BWI Airport  
Baltimore, MD 21240

British Embassy (1)  
Civil Air Attache ATS  
3100 Mass Ave. NW  
Washington, DC 20008

Northwestern University (1)  
Trisnet Repository  
Transportation Center Library  
Evanston, ILL 60201

Director DuCentre Exp DE LA (1)  
Navigation Aerineene  
9141 Orly, France

ANE-40 (2)	ACT-624 (2)	ASW-53B (2)
ASW-52C4 (2)	AAL-62 (2)	AAC-44.4 (2)
APM-13 Nigro (2)	M-493.2 (5)	ACE-66 (2)
AEA-66.1 (3)	Bldg. 10A	ADL-1 (1)
ADL-32 North (1)	APM-1 (1)	ALG-300 (1)
AES-3 (1)	APA-300 (1)	ACT-8 (1)
ANM-60 (2)	AGL-60 (2)	

FAA, Chief, Civil Aviation Assistance Group (1)  
Madrid, Spain  
c/o American Embassy  
APO-New York 09285-0001

Al Astorga (1)  
Federal Aviation  
Administration (CAAG)  
American Embassy, Box 38  
APO-New York 09285-0001

Dick Tobiason (1)  
ATA of America  
1709 New York Avenue, NW  
Washington, DC 20006

MR. JOHN A. LELAND  
DEPT E-29  
DOUGLAS AIRCRAFT CO. 35-14  
3855 LAKEWOOD BLVD.  
LONG BEACH CA. 9084

COMMANDER  
U.S. ARMY AVSCOM  
ATTN: DRSAV-EI(MR. JOHN P. DOW)  
4300 GOODFELLOW BLVD.  
ST. LOUIS, MO. 63120

MR. STAN AMES  
FIRE RESEARCH STATION  
BOREHAMWOOD  
HERTFORDSHIRE WD6 2RL  
ENGLAND

MR. L.C. VIRR  
CIVIL AVIATION AUTHORITY  
BARBAZON HOUSE  
REDHILL  
SURREY RH1 1SQ  
ENGLAND

MR ARTHUR G. THORNING  
CIVIL AVIATION AUTHORITY  
CAA HOUSE  
45-59 KINGSWAY  
LONDON WC2B 6TE  
ENGLAND

MR. RAY YOUNG  
ENGINEERING AND AIR SAFETY DEPT  
AIRLINE PILOTS ASSOCIATION  
1625 MASSACHUSETTS AVE., N.W.  
WASHINGTON, D.C. 20036

MR. LEE HOYT  
WEBER AIRCRAFT CO.  
2820 ONTARIO ST.  
BURBANK, CALIF. 91505

DR. CALYTON E. HATHAWAY  
MONSANTO COMPANY  
800 N. LINDBERG BLVD. MAIL ZONE P3B  
ST. LOUIS, MISSOURI 63166

JULIA M. BAER  
CELANESE FIBERS MARKETING COMP.  
P.O. BOX 32414  
CHARLOTTE, N.C. 28232

DR. LEO P. PARTS  
MONSANTO RESEARCH CORP.  
1515 NICHOLAS ROAD  
DAYTON, OHIO 45407

MR. JAMES O. PRICE  
HEATH TECNA CORP.  
19819 84TH AVE. SOUTH  
KENT, WASHINGTON 98031

MR. RICHARD M. HARRISON  
CUSTOM PRODUCTS CO.  
P.O. BOX 699  
SUN VALLEY, CALIF. 91352

MR. BILL MARTINEZ, MGR. DATA SERV.  
AMI INDUSTRIES, INC.  
P. O. BOX 370  
COLORADO SPRINGS, CALIF. 80901

MR. T. E. WATERMAN  
IIT RESEARCH INSTITUTE  
10 WEST 35TH ST.  
CHICAGO, ILLINOIS 60616

MR. J. J. BRENNEMAN  
FIRE PROTECTION ENGINEER  
UNITED AIRLINES, INC.  
P.O. BOX 66100  
CHICAGO, ILLINOIS 60666

MR. HENRI BRANTING  
FAA HEADQUARTERS  
AWS-120  
800 INDEPENDENCE AVE. S.W.  
WASHINGTON, D.C. 20591

MR. EDWARD L. LOPEZ  
LOCKHEED AIRCRAFT CORP.  
DEPT. 74-75, BLDG. 229-A  
BOX 551  
BURBANK, CALIF. 91503

DR. JAMES E. MIELKE  
SCIENCE POLICY RESEARCH DIV.  
CONGRESSIONAL RESEARCH SERVICES  
LIBRARY OF CONGRESS  
WASHINGTON, D.C. 20540

DR. D. KOURTINES  
CHEMICAL RESEARCH CENTER  
NASA/AMES RESEARCH CENTER  
MOFFETT FIELD, CALIF. 94035

MR. THOMAS MADGWICK  
BRITISH AREOSPACE P.L.C.  
AIRCRAFT GROUP  
WEYBRIDGE-BRISTOL DIVISION  
FILTON HOUSE  
BRISTOL, BS99 7AR ENGLAND

MR. C. HAYDEN LEROY  
TE-10 BLDG. 10-A  
NATIONAL TRANSPORTATION SAFETY BOARD  
WASHINGTON, D.C. 20594

MR. JOSEPH L. BUCKLEY  
FACTORY MUTUAL SYSTEM  
1151 BOSTON-PROVIDENCE TURNPIKE  
NORWOOD, MASS. 02062

Mr. Gary Killion  
ANM-110  
17900 PACIFIC HIGHWAY SOUTH  
C-68966  
SEATTLE, WA 98168

MR. JOHN HOFFMANN  
PORT OF NEW YORK & NEW JERSEY  
AUTHORITY  
ONE PATH PLAZA (4TH FLOOR)  
JERSEY CITY, N.J. 07304

DR. CHARLES R. CRANE  
FAA, CAMI, AAC-114  
P.O. BOX 25082  
OKLAHOMA, OKLA. 73125

MR. ROBERT E. KRAUS  
RAYCHEN CORP.  
300 CONSTITUTION DRIVE  
MENLO PARK, CALIF. 94025

MR. REGINALD DITING  
THE BOEING CO.  
COMMERCIAL AIRPLANE GROUP, 242 DIV.  
P.O. BOX 3702  
SEATTLE, WASHINGTON 98144

MR. JOHN A. BLAIR  
MANAGER, STANDARDS  
E.I. DUPONT DE NEMOURS & CO. 4PP4R  
CHESTNUT EUN  
WILMINGTON, DEL. 19898

DR. JOSEPH L. REED  
E.I. DUPONT DE NEMOURS & CO.  
PLASTICS DEPT.  
ELDMER PARK DIVISION  
WILMINGTON, DEL. 19898

MR. COLLEEN L. POZ  
FOOTBALL CLUB DEPT.  
E.I. DUPONT DE NEMOURS & CO. INC.  
MILWAUKEE, WISCONSIN 53234

MR. GEORGE M. JOHNSON  
CHIEF CHEMIST  
PAN AMERICAN AIRWAYS, INC.  
BLDG. 208 RM. 2228  
J F KENNEDY INT'L AIRPORT  
JAMAICA, NEW YORK 11430

DR. C. PERRY BANKSTON  
ENERGY AND MATERIALS RESEARCH SEC.  
JET PROPULSION LABORATORY  
4800 OAK GROVE DR.  
PASADENA, CALIFORNIA 91103

DR. LLOYD H. BACK  
ENERGY AND MATERIALS RESEARCH SEC.  
JET PROPULSION LABORATORY  
4800 OAK GROVE DRIVE  
PASADENA, CALIFORNIA 91103

MR. JOSEPH A. KRIST  
ATHOL MANUFACTURING CORPORATION  
1350 BROADWAY  
NEW YORK, NEW YORK 10013

DR. A. CARLOS FERNANDEZ-PELLO  
MECHANICAL ENGINEERING DEPARTMENT  
UNIVERSITY OF CALIFORNIA, BERKELEY  
BERKELEY, CALIFORNIA 94720

MR. W.G. DYE  
DIRECTOR OF ENGINEERING  
FAIRCHILD BURNS CO.  
1455 FAIRCHILD DRIVE  
WINSTON SALEM, N.C. 27023

MR. A. F. TAYLOR  
COLLEGE OF AERONAUTICS  
CRANFIELD INSTITUTE OF TECHNOLOGY  
CRANFIELD, BEDFORD MK30AL ENGLAND

DR. ROBERT KEITH  
LABORATORY INDUSTRIAL MEDICINE  
EASTMAN CHEMICAL CO.  
KINGSPORT, TENN. 37662

DR. H.R. DVORAK  
WESSON AND ASSOCIATES, INC.  
510 SOUTH WEBSTER  
POSTAL BOX 1082  
NORMAN, OKLAHOMA 73070

MR. KENTON D. WARNER  
PURITAN-BENNETT CORP. DIV. CO.  
10800 PELUMBA ROAD  
LENEXA, KANSAS 66042



MR. ERICH FELDKIRCHNER  
AIRBUS INDUSTRIE  
HEADQUARTERS, BP NO 33  
31700 BLAGNAC, FRANCE

MR. GEORGE VERYIOGLOU  
SYSTEMS TECHNOLOGY STAFF  
BOEING COMMERCIAL AIRPLANE CO.  
P.O. BOX 3707, MS 77-70  
SEATTLE, WA 98124

MS. DIANE BOULAVSKY  
AMERICAN TEXTILE MFGRS. INSTITUTE  
1101 CONNECTICUT AVE. N.W.  
SUITE 350  
WASHINGTON, D.C. 20036

MR. GREGORY SMITH  
B.F. GOODRICH TECHNICAL CENTER  
P.O. BOX 122  
AVON LAKE, OHIO 44012

MR. MATTHEW FINUCANE  
AVIATION CONSUMER ACTION PROJECT  
P.O. BOX 19029  
WASHINGTON, DC 20036

DR. JAMES G. QUINTIERE  
NATIONAL BUREAU OF STANDARDS  
BLDG. 224, RM. B-356  
WASHINGTON, DC 20234

MR. LEO FISHER  
CREST FOAM  
100 CAROL PLACE  
MOONACHIE, NJ 07074

MR. STAN MARTIN & ASSOC.  
860 VISTA DRIVE  
REDWOOD CITY, CALIF. 94062

MR. PHILIP J. DINENNO  
PROFESSIONAL LOSS CONTROL, INC.  
P.O. BOX 444  
OAK RIDGE, TN 37830

MR. A. L. BRIDGMAN  
GENERAL ELECTRIC CO.  
PLASTICS TECHNOLOGY DEPT.  
1 PLASTICS AVENUE  
PITTSFIELD, MA 01201

MR. JAMES A. MILKE  
DEPARTMENT OF FIRE PROTECTION  
ENGINEERING  
UNIVERSITY OF MARYLAND  
COLLEGE PARK, MD 20742

MR. WALTER T. CLARK, JR.  
CLARK ENGINEERING SERVICE  
312 E. MAIN STREET  
LANSCASTER, TEXAS 75146

MR. JOHN P. REESE  
AEROSPACE INDUSTRIES ASSOCIATION  
OF AMERICA, INC.  
1725 DESALES STREET, N.W.  
WASHINGTON, D.C. 20036

COMMANDING GENERAL  
U.S. ARMY TEST & EVALUATION  
COMMAND  
Attn: DRSTE-AD-A (D. CONLEY)  
ABERDEEN PROVING GROUND, MD. 21005

MR. WILLIAM R. KANE  
SYSTEM ENGINEERING GROUP  
ASD/ENFEF  
WRIGHT-PATTERSON AFB, OHIO 45433

WM. KIRKHAM, PHD., MD, AAC-114  
DOT/FAA CAMI  
AERONAUTICAL CENTER  
P.O. BOX 25082  
OKLAHOMA CITY, OKLAHOMA 73125

MR. A.J. CHRISTOPHER  
ROYAL AIRCRAFT ESTABLISHMENT  
MATERIALS DEPT.  
SOUTH FARNBOROUGH  
HANTS, ENGLAND

MR. HENRY J. ROUX  
PRODUCT FIRE PERFORMANCE  
ARMSTRONG WORLD INDUSTRIES, INC.  
LANCASTER, PA. 17604

MANAGER  
FLIGHT ATTENDANT TRAINING & STANDARD  
WESTERN AIRLINES  
6060 AVION DRIVE  
LOS ANGELES, CALIF. 90009

MR. JOHN ED RYAN  
NATIONAL FOREST PRODUCTS ASSOC.  
50 NORTH FRANKLIN TURNPIKE  
P.O. BOX 314  
HOBOKUS, NEW JERSEY 07423

MR. EVERETT A. TUSTIN  
BOEING COMMERCIAL AIRPLANE COMPANY  
P.O. BOX 3707, M/S 6F-26  
SEATTLE, WASHINGTON 98124

C.M. SLIEPCEVICH  
FLAME DYNAMICS LABORATORY  
UNIVERSITY OF OKLAHOMA  
1215 WESTHEIMER ST.  
NORMAN, OKLAHOMA 73069

MR. R.G. CLODFELTER  
AFWAL/POSH  
WRIGHT-PATTERSON AFB  
OHIO 45433

MR. LOUIS FRISCO  
WIRE & CABLE DIVISION  
RAYCHEM CORP.  
300 CONSTITUTION DRIVE  
MENLO PARK, CALIF. 94025

DR. EDWIN SMITH  
OHIO STATE UNIVERSITY  
140 W. 19TH AVE.  
COLUMBUS, OHIO 43214

BERNARD GREND AHL, MGR. TECH. SERV.  
AEROSPACE DIVISION  
UNIVERSAL OIL PRODUCTS CO.  
BANTAM, CONN. 06750

MR. WILLIAM SNODDY  
AMERICAN AIRLINES  
P.O. BOX 51009 MAIL STOP #10  
TULSA, OKLAHOMA 74151

A. TEWARSON  
FMRC  
1151 BOSTON-PROVIDENCE T/PKE  
NORWOOD, MASS. 02062

MRS. CHARLOTTE GEBHART  
ROHM & HAAS CO.  
INDEPENDENCE MALL WEST  
PHILADELPHIA, PA. 19105

DR. ROSALIND C. ANDERSON  
ARTHUR D. LITTLE, INC.  
ACORN PARK  
CAMBRIDGE, MASS. 02140

MR. FRED JENKINS, ANM-1301  
FEDERAL AVIATION ADMINISTRATION  
4344 DONALD DOUGLAS DRIVE  
LONG BEACH, CALIFORNIA 90808

MR. MATTHEW M. MCCORMICK  
NATIONAL TRANSPORTATION SAFETY BD.  
BUREAU OF TECHNOLOGY  
WASHINGTON, D.C. 20594

MR. DAN GROSS  
B-66 TECHNOLOGY BUILDING  
NATIONAL BUREAU OF STANDARDS  
WASHINGTON, D.C. 20234

MR. A. DELMAN  
THE WOOL BUREAU, INC.  
TECHNICAL SERVICES CENTER  
225 CROSSWAYS PARK DRIVE  
WOODBURY, L.I., NEW YORK 11797

DR. JAMES M. PETERSON  
THE BOEING CO.  
MS/73-43  
SEATTLE, WASHINGTON 98124

DR. L. BENISEK  
INTERNATIONAL WOOL SECRETARIAT  
TECHNICAL CENTER, VALLEY DRIVE  
ILKLEY, WEST YORKSHIRE, LS29 8PB  
ENGLAND

DR. JOHN O. FUNDERSON  
E.I. DUPONT De NEMOURS  
P.O. BOX 1217  
PARKERSBURG, W. VA. 26102

DR. FUMIHARU SAITO  
BUILDING RESEARCH INSTITUTE  
MINISTRY OF CONSTRUCTION  
TATEHARA-1 OHG-MACHI  
TSUKUBA-GUN  
IBARAKI PREFECTURE, JAPAN

MR. PETER MEINLEM  
CIVIL AIR ATTACH (SAFETY)  
BRITISH EMBASSY  
3100 MASSACHUSETTS AVE. NW  
WASHINGTON, D.C. 20008

T.F. LAUGHLIN, JR.  
LOCKHEED-CALIFORNIA CO.  
11798-01, BAYVIEW, A-1  
P.O. BOX 501  
BURBANK, CALIFORNIA 91506

DR. CHARLES P. LAZZARA  
US BUREAU OF MINES  
PGH. RESEARCH CENTER  
P.O. BOX 18070  
PITTSBURG, PA. 15236

KIRKE COMSTOCK  
MANAGER OF INTERIOR ENGINEERING  
UNITED AIRLINES MAINT. OPER. CENTER  
ENGINEERING DEPT.  
SAN FRANCISCO INTERNATIONAL AIRPORT  
SAN FRANCISCO, CALIF. 94128

DR. JOHN LEVERTON  
CIVIL REGULATIONS MANAGER  
CIVIL BUSINESS GROUP  
WESTLAND HELICOPTERS, LTD.  
YEOVIL, BA20 2YB  
SOMERSET, ENGLAND

D.A. RADICE  
MANAGER, FLEXIBLE SALES  
CPR DIVISION OF UPJOHN CO.  
555 ALASKA AVE.  
TORRENCE, CALIF. 90503

DR. DALE G. ONDERAK  
JOHN SCHNELLER & ASSOCIATES  
6019 POWDERMILL ROAD  
KENT, OHIO 44240

MR. MICHEAL TYLER  
AVIATION SAFETY BUREAU  
TRANSPORT CANADA  
OTTAWA, ONTARIO, CANADA K1A0N8

MR. MIKE BAUCCIO  
U.S. ARMY AVIATION R&D COMMAND  
AVSCOM/DRSAV-US  
4300 GOODFELLOW BLVD.  
ST. LOUIS, MISSOURI 63120

MR. CHARLES W. MCGUIRE  
DEPT. OF TRANSPORTATION  
400 7TH STREET S.W.  
WASHINGTON D.C. 20590

MR. VYTO BABRAUSKAS  
NATIONAL BUREAU OF STANDARDS  
BLDG. 224, ROOM A-345  
WASHINGTON D.C. 20234

MR. A.T. PEACOCK  
DOUGLAS AIRCRAFT COMPANY  
INTERNAL MAIL CODE 35-41  
3855 LAKEWOOD BLVD.  
LONG BEACH, CA. 90846

MR. PASCAL DRANITSARIS  
ONTARIO RESEARCH FOUNDATION  
SHERIDAN PARK RESEARCH COMMUNITY  
MISSISSAUGA, ONTARIO, CANADA  
L5K1B3

MR. ERIC W. SIMMONS  
ONTARIO RESEARCH FOUNDATION  
SHERIDAN PARK RESEARCH COMMUNITY  
MISSISSAUGA, ONTARIO, CANADA  
L5K1B3

MR. V.W. BALLENGER  
DIRECTOR, ENGINEERING AND MAINT.  
AIR TRANSPORT ASSOCIATION  
1709 NEW YORK AVE., NW  
WASHINGTON, D.C. 20006

MR. JAMES H. KEELER  
GENERAL ELECTRIC COMPANY  
ONE PLASTICS AVE.  
PITTSFIELD, MASSACHUSETTS 01201

MR. WILLIAM K. GREER  
GENERAL ELECTRIC COMPANY  
ONE PLASTICS AVE.  
PITTSFIELD, MASSACHUSETTS 01201

MR. JIM BROWN  
GENERAL DYNAMICS ELECTRIC BOAT DIV.  
STATION C62  
EASTERN POINT ROAD  
GROTON, CONN. 06340

MR. CHARLES MACALUSS  
U.S. TESTING  
5555 TELEGRAPH RD.  
L.A., CA. 90040

MR. JOHN R. POWERS  
DELTA AIRLINES, INC  
HARTSFIELD ATLANTA  
INTERNATIONAL AIRPORT  
ATLANTA, GEORGIA 30320

MR. STEVE WALDRIP  
REPUBLIC AIRLINES  
7500 AIRLINE DRIVE  
MINNEAPOLIS, MINNESOTA 55450

MR. S.M. HOOPER  
EASTERN AIRLINES  
MIAMI INTERNATIONAL AIRPORT  
MIAMI, FL. 33146

END

12-86

DTIC